

# PowerCost Monitor™



## Unsupported/Incompatible Meters

### FOCUS

---

Landis & Gyr FOCUS/ALF meter.

(Trilliant Radio often installed)

No infrared (ir) pulse for the sensor to pickup



### Plate Cover

---

Standard Disk meter with AMR plate covering disk.

No location for the sensor to be installed





## ELSTER A3TL

---

**Elster A3TL Does not transmit the Watt pulse**  
ANSI (Silver raised port) does not output IR pulse



No Pulse Emitted!

## MT200/100 Hybrid

---

**Schlumberger MT200/100 Does not transmit the Watt pulse**  
ANSI (Silver raised port) does not output IR pulse



